



MLEF INPUT TERMINAL INSTALLATION INSTRUCTIONS

INSTALLATION


- 1 REMOVE END CAP FROM END OF TRACK



- 2 SLIDE THE TRACK CONNECTOR (a) INTO THE SLOT ON THE BACK OF THE TRACK.




- 3 CAREFULLY LINE UP PIN CONNECTORS(b) WITH PIN CONNECTOR HOLES(c).




ATTENTION:

WHEN JOINING TRACKS OR ACCESSORIES UTILIZING PIN CONNECTORS, MAKE SURE PINS ARE HORIZONTAL AND LINE UP WITH PIN CONNECTOR HOLES. YOU MAY NEED TO GENTLY PUSH UP OR DOWN ON THE PINS SO THEY LINE UP CORRECTLY. FAILING TO DO THIS MAY RESULT IN PINS MISSING THE PIN CONNECTOR HOLES AND LOSS OF THE 24 VOLT CONNECTION.




- 4 ATTACH MLEF TO THE TRACK AND SECURE WITH SET SCREWS




MLEF INPUT TERMINAL INSTALLATION INSTRUCTIONS

ATTENTION: IF YOU WANT TO CHANGE THE DIRECTION OF THE POWER CABLE, FOLLOW THE STEPS BELOW


1 SLIDE OUT THE COVER PLATE



2 KNOCK OUT THE WIRING HOLE ON SIDE COVER



3 PULL THE WIRE THROUGH THE HOLE ON SIDE COVER



4 SLIDE COVER PLATE BACK INTO THE GROOVE

